

An indication of internal hydraulic hose failure. Hydraulic Hose assemblies having blisters on the outer shell must be replaced immediately.







HSAC.ca



Safety courses



First Aid for Fluid Injection Injury

Copyright © 2016 International Hydraulic Safety Authority